

**Coast Aviation**

Airport Road, Merritt Island, Fl 32952. Tel: 321/453-2222

4 February 2011 Reg: N9277W Tach: 1192.88

	<u>Serial #</u>	<u>Total Time</u>	<u>TSMO</u>
Time:	2810951	3333.6	
:	L-11422-40	3325.34	42.94
	CH3433	3325.34	42.94

Verify that an **Annual inspection** has been performed on this engine and propeller in accordance with FAR part 43 appendix D. and Lycoming M.M. Drained oil and replenished with 5 quarts Aeroshell W100. Replaced oil filter with new CH 48110-1 checked oil level. Replaced open old oil filter, no metal particles noted. Cleaned, gapped, tested and replaced spark plugs. Inspected hoses, exhaust, fuel and induction systems and accessories. Replaced air filter with new BA-3 filter. Performed differential pressure test results as follows:

80 #2 76/80 #3 76/80 #4 75/80 #5 77/80 #6 78/80

Inspected and researched through issue 2011-03 No engine or propeller AD's due at this time. Run up completed all indications normal. Engine and propeller determined to be airworthy and returned to service.

  
Kenneth D. Wilson 31098598 IA

--	--	--	--